

Gehl SL4510 Maintenance - Offline Parts List

Store: NAPA Auto Parts

Prepared for: Commander Cooper (Field Deployment)

NAPA SME

Universal Fuel Tank Bushing

NAPA Part #: SME 707461D (or SME 707461)

Amazon Search: [Oregon 07-392](#)

Size: Fits 33/64" hole, accepts 3/8" elbow

CRITICAL: Replaces broken Gehl N073024

NAPA SME / Hardware

90-Degree Fuel Elbow Plug

Amazon Search: [33/64" Universal 90-Degree Kit](#)

Requirement: Must press-fit tightly into the SME 707461D bushing.

CRITICAL: Replaces broken Gehl tube N073183

NAPA Auto

Engine Oil Filter (Ford I-98)

Part #: Fram PH7 (or NAPA Gold Cross-Reference)

Gehl OEM: 611990

Notes: Required for SN <= 5500 filter service day.

NAPA Hyd

AW-46 Hydraulic Fluid

NAPA Part #: NHF 85805 (5 Gallon Bucket)

Notes: Premium AW-46 Anti-Wear. Do not use 85-101 (R&O).